The Boeing Company
P.O. Box 516
St. Louis, MO 63166-0516
(314) 232-0232 TELEX 44-857

NOV 0 4 2002 RCAP

464C-5332-JWH 30 October 2002



Mr. Jerome Johnson U.S. Environmental Protection Agency Region VII 901 North Fifth Street Kansas City, Kansas 66101

Enclosure: Corrective Action Quarterly Progress Report-Third Quarter 2002

Dear Mr. Johnson:

The enclosed Quarterly Progress Report is submitted as required by Section XI. of the Corrective Action Conditions of the Hazardous Waste Management Facility Permit, Number MOD 000 818 963. Three copies of the report will also be submitted to the Missouri Department of Natural Resources as required under the terms of the permit.

Please contact me should you need additional information.

Sincerely,

Joseph W. Haake, Group Manager

Environmental and Hazardous Materials Services

Dept. 464C, Bldg. 220, Mailcode S221-1400

(314) 232-6941

R00407409 RCRA RECORDS CENTER

Quarterly Progress Report for Third Quarter 2002

Description of the work completed

Third quarter sampling of the monitoring wells at SWMU #17 and the Former Fabrication Operations Facility was conducted in August.

Summary of all findings

None

Summary of all problems or potential problems and actions taken to rectify problems

None

Projected work for the next reporting period

Upon MDNR approval, install additional borings at SWMU #17 as, described in the Annual Monitoring Report, to determine the extent of contamination to the south.

Continue quarterly monitoring well sampling at SWMU #17 and at the Former Fabrication Operations site.

Instances of noncompliance with the corrective actions of the permit

None

Quarterly Progress Report for Third Quarter 2002

Description of the work completed

Third quarter sampling of the monitoring wells at SWMU #17 and the Former Fabrication Operations Facility was conducted in August.

Summary of all findings

None

Summary of all problems or potential problems and actions taken to rectify problems

None

Projected work for the next reporting period

Upon MDNR approval, install additional borings at SWMU #17 as, described in the Annual Monitoring Report, to determine the extent of contamination to the south.

Continue quarterly monitoring well sampling at SWMU #17 and at the Former Fabrication Operations site.

Instances of noncompliance with the corrective actions of the permit

None